

Agenda
PWR and BWR LOCA PIRT for High Burn-up Fuel (1st Meeting)
11545 Rockville Pike, North Bethesda, MD 20852
May 31-June 2, 2000

Meeting Objectives

- Present overview on PWR LOCA phenomena to panel
- Present overview on BWR LOCA phenomena to panel
- Present overview on cladding phenomena to panel
- Prepare PWR and BWR LOCA phenomena lists
 - Entire panel consider LOCA phenomena list
 - Categories A and C: Analytical
 - Categories B and D: Experimental
- Develop LOCA importance ranking
- Assess applicability of LOCA ballooning and rupture PIRT to BWR ATWS
- Review status of BWR ATWS report and receive initial panel comments

Wednesday, May 31, 2000 (Check-in at 8:15 AM; Meeting begins at 8:30 AM)

8:15 AM	Check-in at 1 st Floor Guard Station
8:30	Welcome, Meeting Objectives, Agenda Review
8:45	PWR LOCA Overview (L. Hochreiter)
9:45	BWR LOCA Overview (J. Andersen)
10:45	Break (15 minutes)
11:00	Cladding Phenomena Overview (M. Billone)
Noon	Lunch (60 minutes)
1:00 PM	Category A figure of merit and phenomena list definition (Peddicord/Hochreiter, Panel)
2:00	Category B figure of merit and phenomena list definition (Motta, Panel)
3:00	Break (15 minutes)
3:15	Category C figure of merit and phenomena list definition (Peddicord/Hochreiter, Panel)
4:15	Category D figure of merit and phenomena list definition (Motta, Panel)
5:15	Follow-up on Action Items <ul style="list-style-type: none">● Writing assignments: experiment summaries● Writing assignments: BWR fuel descriptions at burnup and during ATWS

Thursday, June 1, 2000 (Check-in at 8:15 AM; Meeting begins at 8:30 AM)

8:15 AM	Check-in at 1 st Floor Guard Station
8:30	Breakout group assignments and room locations
8:45	Breakout groups (Categories A&C and B&D) <ul style="list-style-type: none">● Finalize phenomena list● Complete definitions for phenomena● Confirm Figure of Merit (Evaluation Criterion) and question format● Determine if applicability and uncertainty evaluations needed● Begin ranking, applicability, and uncertainty discussions

Continued

Thursday, June 1, 2000 (afternoon)

Noon	Lunch (60 minutes)
1:00 PM	Breakout groups continue (Categories A&C and B&D)
4:00	Reconvene for breakout group status reports
	<ul style="list-style-type: none">● Categories A&C (Peddicord/Hochreiter)<ul style="list-style-type: none">○ Status○ Issues and Needs○ Estimate of time needed to complete● Categories B&D (Motta)<ul style="list-style-type: none">○ Status○ Issues and Needs○ Estimate of time needed to complete
5:00	Plans for remainder of meeting
5:15	Adjourn

Friday, June 2, 2000 (Check-in at 8:15 AM; Meeting begins at 8:30 AM)

8:15 AM	Check-in at 1 st Floor Guard Station
8:30	Breakout groups continue (Categories A&C and B&D)
Noon	Lunch (45 minutes)
12:45	Reconvene for breakout group status reports
	<ul style="list-style-type: none">● Categories A&C (Peddicord/Hochreiter)<ul style="list-style-type: none">○ Status○ Issues and Needs○ Estimate of effort needed to complete● Categories B&D (Motta)<ul style="list-style-type: none">○ Status○ Issues and Needs○ Estimate of effort needed to complete
1:45	Discussion: Applicability of PWR and BWR LOCA ballooning and rupture phenomena to BWR ATWS
2:30	Panel comments on BWR ATWS PIRT tables
3:00	Adjourn